



**Log of Borehole: TB-4**

**Logged by:**

**Client: Washington Department of Ecology Ecology PM: Bill Fees**

SUBSURFACE PROFILE				SAMPLE				Well Completion Details
feet (bgs)	feet (MSL)	Symbol	Description	Number	Type	N-Value	Recovery	
0	1218.1 0.0		Ground Surface					
2			SILT, ML, with leaves in upper 2" , medium brown, slightly moist	01			26"	
4								
6				02			30"	
8								
10	1208.1 10.0		CLAY, CL, medium brown with iron oxide mottling	03			44"	
12	1206.6 11.5		GRAVEL, GM, well rounded, moist					
	1205.6 12.5		Silty CLAY , CL, with trace gravels					
14	1204.6 13.5		Silty GRAVEL, GM, medium gray brown with some iron oxide staining and mottling.	04			32"	
16								
18				05			0	
	1198.9 19.2		Drilling refusal at 19.2' bgs					
20								

Drilled By: Environmental West Exploration

Drill Method: Geoprobe

Drill Date: 10/15/01

Hole Size:

Sheet: 1 of 1